DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/Ala Rte: 80 PM: 13.2/13.9

File #: 69.28

WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-012085 Address: 333 Burma Road **Date Inspected:** 30-Jan-2010

City: Oakland, CA 94607

OSM Arrival Time: 1900 **Project Name:** SAS Superstructure **OSM Departure Time:** 700 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name: See below **CWI Present:** Yes No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A N/A **Electrode to specification:** Yes No Weld Procedures Followed: Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No Yes No N/A **Delayed / Cancelled:**

34-0006 **Bridge No: Component:** Tower Components

Summary of Items Observed:

On this date Caltrans OSM Quality Assurance Inspector (QA Inspector) George Goulet was present during the times noted above for observations relative to the work being performed.

Bay 10

This QA Inspector randomly observed the following work in progress in Bay 10:

SMAW repair welding of weld joint SSTL4-1I/L-96 located inside PCMK south tower, lift 4, skins A/E corner, corner closure plate to top of 135M double diaphragm. Welder was identified as 050038. ZPMC QC was identified as CWI Gong Liang Zhu (QC1). The welding variables recorded by QC1 appeared to comply with WPS-485-SMAW-3G(3F)-repair. Also present at this location and appearing to be monitoring the welding related operations was ABF Representative Li Nan.

SMAW repair welding of weld joints SSTL4-1F/L-109, 116 located inside PCMK south tower, lift 4, skin A to top of 123M double diaphragm. Welder was identified as 053829. ZPMC QC was identified as QC1. The welding variables recorded by QC1 appeared to comply with WPS-345+485-SMAW-2G(2F)-repair-2. Also present at this location and appearing to be monitoring the welding related operations was ABF Representative Li Nan.

Bay 11

No welding was observed being performed in Bay 11.

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

Summary of Conversations:

No significant conversations.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Skyler Guest, 150-0042-2360, who represents the Office of Structural Materials for your project.

Inspected By:	Goulet,George	Quality Assurance Inspector
Reviewed By:	Dawson,Paul	QA Reviewer